




Atwood Mobile Products
4760 Hawthorn Drive - Rockford, IL 61109-1296
PHONE: 815-877-5700 FAX: 815-877-7469
INTERNET: <http://www.atwoodmobile.com>

INFORMATION NOTICE

WEDGEWOOD RANGE BURNER ALIGNMENT

(OPEN BURNER)

Effective 5/3/01



INSPECTION AND ALIGNMENT OF OPEN COOKTOP BURNERS

Cooktop burners should be inspected for proper alignment. The burner is properly aligned when the burner is centered in the hole of the cooktop. Improper alignment may cause flame impingement and damage the cooktop.

In order to properly align the burner; loosening the screw (A) holding the burner's bracket to the burner box with a phillips screw driver. Center the burner (B) in the opening (C) and tighten the screw.

If you have any questions please contact the Atwood Service Department at 1-800-825-4328.